

Valve Seat, Refacing



Caution

The valve seats are not to be refaced due to the close tolerances.